


BAT 556/557 OR 561 pH/ORP SENSORS WITHOUT SOLUTION GROUND
WIRED TO
ROSEMOUNT 54e TRANSMITTERS



REVISIONS					DIMENSIONS IN INCHES		
REV	DATE	DESCRIPTION	DWN	APVD	TOLERANCES UNLESS OTHERWISE SPECIFIED		
					DECIMALS	FRACTIONS	
					.0000 +/- .0005	+/- .015	
					.000 +/- .005	ANGLES	
					.00 +/- .010	+/- 30MIN	
					.0 +/- .15		
					DRAWING BY. HWM		
					SCALE	DATE	SIZE
					NONE	12/10/01	A

WIRING OF BAT COMBINATION
pH/ORP SENSORS TO
ROSEMOUNT 54e TRANSMITTER

B ARBEN
A ANALYZER
T ECHNOLOGY

DRAWING NO. 2P0031


CHECKED

APPROVED

PH(775)882-7900 FAX(775)883-6388

1 OF 2

BAT 556/557 OR 561 pH/ORP SENSORS WITH SOLUTION GROUND WIRED TO ROSEMOUNT 54e TRANSMITTERS



REVISIONS					DIMENSIONS IN INCHES		
REV	DATE	DESCRIPTION	DWN	APVD	TOLERANCES UNLESS OTHERWISE SPECIFIED		
					DECIMALS	FRACTIONS	
					.0000 +/- .0005	+/- .015	
					.000 +/- .005	ANGLES	
					.00 +/- .010	+/- 30MIN	
					.0 +/- .15		
					DRAWING BY: HWM		
					SCALE	DATE	SIZE
					NONE	12/10/01	A

WIRING OF BAT COMBINATION pH/ORP SENSORS TO ROSEMOUNT 54e TRANSMITTER

B ARBEN **A** NALYZER **T** ECHNOLOGY

DRAWING NO. 2P0031

CHECKED

APPROVED

PH(775)882-7900 FAX(775)883-6388

2 OF 2